


Structurally Deficient Bridges on the National Highway System 24th Congressional District of California, 2003



Structure Number	Road	Location
1 51 0073L	ROUTE 101	05-SB-101-70.91
2 51 0073R	ROUTE 101	05-SB-101-70.91
3 51 0094	STATE ROUTE 1	05-SB-001-13.34
4 51 0118R	ROUTE 1	05-SB-001-R34.76
5 51 0221R	U.S. HIGHWAY 101	05-SB-101-R56.64
6 52 0183	STATE ROUTE 126	07-VEN-126-19.26
7 52 0260R	STATE ROUTE 126 EB	07-VEN-126-R12.04-SPA

Legend

- Structurally Deficient Bridges
- Cities
- Airports
- Amtrak Stations
- Interstate Highways
- US Highways
- State Highways
- Amtrak Routes
- Other Rail Lines
- Navigable Waterways
- California District 24
- Urbanized Areas
- Park Facilities
- Military Bases



The bridges displayed on this map represent the results of a combined BTS/FHWA effort to geocode bridges from the FHWA's 2001 National Bridge Inventory. Of the 6,643 structurally deficient bridges nationwide, 416 could not be geolocated because of insufficient data. Structurally deficient bridges are not necessarily unsafe: all public road bridges receive safety inspections every two years. The bridges listed were categorized as structurally deficient at the time the maps were developed.